

**T86 Control parts pricing**

Q2LC

	<b>Sell</b>	<b>RRP</b>	<b>Supplier</b>
AP replacement front rotor - DBA52935.1S	\$ 330.00		TAA
TGR series DBA42656S-10 Rear rotor	\$ 229.00		TAA
DBA4650S front rotor for STD Caliper	\$ 195.00		TAA
DBA42663S rear rotor for STD caliper	\$ 195.00		TAA
DBA Front Full kit to replace AP - 5000BLKS	\$ 490.00		TAA
DBA Rotor 5000.1S	\$ 249.00		TAA
Circo S99 Front pads MB1648.17 (AP Calipers)	\$ 360.00	\$ 380.00	TAA
Circo S83 Rear pad MB680 (AP Calipers)	\$ 278.00	\$ 298.00	TAA
Circo S99 Front MB1180 STD Calipers (GTS)	\$ 269.00	\$ 289.00	TAA
Circo S83 Rear pad MB1718 STD Calipers (GTS)	\$ 225.00	\$ 247.00	TAA
Circo S83 Rear pad MB1330 STD Calipers (GT)	\$ 225.00	\$ 247.00	TAA
Koya 18x8 +42 race wheels	TBA		T86 Shop
SRE Full Exhaust system	\$ 1,800.00		Scotts Rods
Engine Oil Cooler	TBA		T86 Shop
Dunlop Direzza DII	\$ 290.00		DMA OZ
T86RS Shocks inc springs	\$ 2,995.00		MCA